

Instruction Sheet No. 1

Terms and Conditions of Delivery

Solid waste which does not require crushing

– Loose material –

Additional: [Appendix to the Delivery Conditions of Instruction Sheets No. 1, 2, 3 and 5: Materials, which are excluded from Bunker, Shredder or Paste \(Exclusion List\)](#)



In advance of any delivery a detailed waste description in English or German language has to be provided (safety data sheet, analysis). Alternatively a sample of the waste may be submitted. Information about modifications of the waste must be submitted immediately without request.

Delivery Conditions:

- Waste must be solid or semisolid, no free liquids in the waste
- Waste for shredder (Instruction Sheet No. 2) must be strictly separated from waste without shredding (Instruction Sheet No. 1)
- Max. length of parts: 25 cm
- No solid metal parts, sheet metal, iron pipes and rods, gears and castings
- No closed metal drums or cans
- Not dusty, not reactive, not smelling, not toxic (6.1)
- No spray cans, aerosols
- **Exclusion List:** Materials which REMONDIS SAVA is not allowed to accept or which must be excluded from the bunker waste. They are documented in the [Appendix to the Delivery Conditions of Instruction Sheet 1, 2, 3 and 5: Materials, which are excluded from Bunker, Shredder or Paste \(Exclusion List\)](#).

Prior agreement must be obtained for deviation from the conditions mentioned above

Regarding premixed waste (EWC 19 02 04*) the following parameters must be fulfilled:

- Flashpoint >21°C
- Mercury (Hg) < 10 ppm, if the concentration is higher, please enquire
- The preparing facility should have the following installations: Shredder, mixer, laboratory

Waste declaration

Waste producers have to analyze and declare the following parameters:

- Consistency (solid, liquid, pasty)
- Calorific value
- Ash residue
- Mercury
- Halogenes (single values or fluorine, chlorine, bromine, iodine)
- Total sulphur
- Content of alkali metals (single values of sodium and potassium)
- Content of organic silicon

For further information please contact:

REMONDIS SAVA GmbH // Ostertweute 1 // 25541 Brunsbüttel // Germany // T +49 4852 8308-0 // F +49 4852 8308-12
info.sava@remondis.de // remondis-sava.com